



Technical Bulletin
Rev. 1/4/07

Laminated Glass - Bugs

A problem has long existed with the identification of laminated glass used in hazardous locations. Laminated glass manufacturers usually “bug” one or two corners of a stock sheet. Obviously, if several small lites are cut from a large stock sheet, only one or two lites will have the manufacturer’s “bug”.

The building codes allow glazing contractors to “bug” laminated glass. The Americas Glass Association has “Bug-it”™ kits available that allow the installer to “bug” each lite of laminated glass as he installs it.

For further information, contact the staff at:

Americas Glass Association
P. O. Box 2550
Placerville, CA 95667

Phone: 530/ 642-0992
FAX 530/ 642-0993